


The materials used in insulated widow glass unit.

This does not apply to what is called swiggle rap or super seal.



Signs that the seal has broken and reason that an insulated unit will break its seal.

All weather conditions play havoc on the seal but none more-so than high heat accompanied with high humidity. The northern portions of the United States do not experience as much moisture glass as the southern regions

